# **Boler Axle Replacement**

## Overview

My axle is over 50 years old. It might be time to replace it.

# Replacement Axle

From lan's web site, he recommends the following axle:

#### **Replacement Axle Specifications**

Dexter #9: 2000 lb - 2200 lb with brakes

Bolt circle: 5x4.5

Start angle: 10 deg up

Bracket type: Low Profile (if extra ground clearance needed use high profile brackets)

Bracket spacing (outside to outside frame): 48

Hub face to Hub Face: 63

NOTE: Double check all measurements on your axle

### Observations

It appears that my axle is welded to the frame. I would need to cut the old axle off and find a new way to mount a new axle.

Reference	URL
Boler.ca	https://www.boler.ca/2017/05/19/torsion-axle/
Paul Neumeister, Fibreglass RV Parts, Repairs, & Service	http://www.fibreglass-rv.ca/index.html
Fiberglass RV Forum	https://www.fiberglassrv.com/forums/f72/boler-1300-axle-replacement-41807.html
Boler Axel & Frame	https://ourboleradventures.wordpress.com/2018/05/24/boler-axel/
Dexter Axle	https://www.dexteraxle.com/Products/Torsion-Axles/Torflex-Light-Duty