

Capturing output from serial port

Determine the USB port

```
> ls -l /dev/cu_*
```

Configure the defaults for minicom

```
> minicom -s
```

META-Z key is ESC-Z

META-Z

U - Add Carriage return

Capture output to a file

```
> minicom -C ~/serial.out.txt -D /dev/cu.wchusbserial1420 -b 115200
```