

Moen Motionsense Kitchen Faucet

- [Specifications](#)
- [Parts](#)
- [Repairs](#)
 - [Leaking Handle](#)
- [References](#)



Specifications

Specification	Details
Make	Moen
Model #	87359ESRS
Manufactured Date	12/3/12
Model	Arbor Motionsense Two-Sensor Touchless One-Handle Pulldown Kitchen Faucet

Parts

Part	Description	Image	Price
------	-------------	-------	-------

169031	AC Adapter with Power Splitter for Arbor Single-Handle High Arc Pull-Down Kitchen Faucet		\$158.16 CAN
OEM Power Supply	<p>Omnihil 2.5 Meter AC/DC Power Adapter Compatible with Moen Brantford MotionSense 7185EC, 7185ESRS, 7185EORB Power Supply Charger, Compatible Part...</p> <ul style="list-style-type: none"> • Adapter Rating: World Wide 100V ~ 240V 50/60Hz - UL LISTED -2.5 Meter Total Cord Length • All products are tested to exceed/meet standard specification • OVP, OCP, SCP Protection (OVP: Over Voltage output Protection. OCP: Over Current output Protection. SCP: Short Circuit output Protection) • Output 12V DC, 1.5A <p>https://www.amazon.ca/gp/product/B08KB4KNYY/ref=ppx_od_dt_b_asin_title_s00?ie=UTF8&psc=1</p>		\$18.71 CAN

Repairs

Leaking Handle

We had a small trickle of water coming from the handle. Not all the time but some time when on.

To fix, we need to remove the handle using an Allen key and tighten the fastening bolt using an adjustable wrench.

Turn clockwise anywhere from 1/4 turn to 1/2 turn should do it.



References

Reference	URL
Installation	https://www.youtube.com/watch?v=fHze1DRMvfc