

POOL ENCLOSURE INSPECTION REPORT

Pool Enclosure By-law 2013-39

Address 19 FINDLAY CRES						
Owner/Contractor MEHAN, JENNIFER Permit No. 1902990						
✓ Your pool enclosure has been inspected and approved for placement of water.						
	Inspection did not pass. Please have the noted infractions corrected and call for a re-inspection.					
	Gate/Enclosure insu	officient height	11, 20(a)		Opening 100mm or greater through or under Gate/Enclosure	20(b), 37(c)
	Gate or Door not selatch incorrect locat	lf-closing, self-latching or ion	21(b),(c), 25(a)		Enclosure is climbable	20(e),(f)
	Gate or Door not clo in use	Door not closed and locked when pool not			Enclosure not constructed to the specifications of this by-law	28,29,30
	Hot tub not equippe or an enclosure that	d with approved safety cover meets this by-law	33		Above Ground Pool enclosure not acceptable	31(2)
		r not fastened and/or not rhen hot tub not in use	34		Temporary enclosure not constructed to specifications of this by-law	37
Temporary enclosure approved. Call for re-inspection within 14 days. There is no record of a pool enclosure permit. Obtain a pool enclosure permit. Pool shall not be filled with water prior to approval of the enclosure.						
INSPECTION COMMENTS: Permit Description: Install an enclosure for an above ground pool (rear yard) Received a copy of the hydro clearance letter. All previous deficiencies have been addressed. No further inspection required. File to be closed. **Please note that it is the owner's responsibility to maintain the pool enclosure in accordance with By-law 2013-39 and maintain the enclosure locked at all times when the pool area is not in use.						
Receiv	ved By John Mehan <jmehan@yahoo.com></jmehan@yahoo.com>					
Inspec	etor	Louise Langlois Louise.langlois@otta Tel: 613-580-2424 Ex			Date Requested 21-Nov-2022	_
		1 ci. 013-300-2424 E			Date Completed 21-Nov-2022	✓ Same